

Technical Specification Bulletin Number 222

Fuel Type
Oil

Date of Issue
May 2010

Edition
1



Oil Control Knob Replacement

Page Number 1

Oil Control Knob Replacement for 38536

The plastic oil control knob (38536) which has a small retaining grub screw has been discontinued by the manufacturer and a replacement has to be used in its place (MS2322). The surrounding bezel remains in place on the stove.



Discontinued Control Knob

In place of the original is a metal control knob which comes complete with a grub screw and small allen key.



The control knob should be slid over the shaft and the grub screw aligned with the dimple on the shaft so that when tight the control knob will not slip on the shaft.



← Dimple into which the grub screw must locate

